
MACHINE ROOM

3 discrete wires from controller in machine room for each landing.



Plug in the UP output connector to the UP arrow LED and plug in the DN output to the DOWN arrow LED. Wire in the UP, COM and DN input from the controller in the machine room.